

**The Road Traffic Regulations apply on our premises**



Walking speed applies on the entire premises. \*1 - 3  
Walking speed is in force on the entire premises. In certain areas there is no trespassing. (Firing Hoods) \*1



No stopping in front of fire extinguishing devices as well as especially marked areas.



Parking only in the marked or assigned areas.



No stopping on marked evacuation routes.

**Conduct in case of emergencies**

**EVERYONE** is obligated to render first aid in case of injuries, damage and accidents of any kind.



**Environment Protection**

We are assuming responsibility for society and the environment. Consciousness for the environment will be sharpened by avoidance of waste and economical use of resources. Therefore please note:



Packing material (paper, cardboard, foil, styrofoam etc.) must be collected immediately. Waste must be taken by its generator and disposed of, outside the plant premises.



The use of hazardous materials must be reduced to a minimum.



Waste water is only allowed to be fed into the plant wastewater network after prior authorization.

**Bans on the entire plant premises**



Bringing animals on the grounds is prohibited.



No smoking in the office and social areas, as well in marked areas and aggregates \*1-3, especially at the blasting bunker and the igniter storage. \*1



Fire and open lighting is basically prohibited. Especially at the blasting bunker and igniter storage. Welding, angle grinding / torch cutting only with an authorization certificate and relevant PSE \*1

Fire and open lighting is prohibited. Welding, angle grinding or torch cutting only with an authorization certificate and relevant PSE. \*2 \*3



Alcohol prohibition applies in principal.



No staying in fenced hazardous areas.. \*1



Mobile phones are not allowed at the blasting bunker and igniter storage.. \*1

**Prior to the delivery to us, please in your own interest, watch for:**

- A-Sign in place?
- A proper load safety
- Maintaining the maximum permissible total weight
- The rules of the road are maintained



**Safety Information and Framework Conditions**



\*1 = Dortmund, Lütje Heidestraße 115    \*2 = Osnabrück, Rheinstraße 103 – 105    \*3 = Osnabrück, Mindener Straße 158a    \*4 = Schlackeplatz Bous

\*1 = Dortmund, Lütje Heidestraße 115    \*2 = Osnabrück, Rheinstraße 103 – 105    \*3 = Osnabrück, Mindener Straße 158a    \*4 = Schlackeplatz Bous

## Basic Regulations

- Visitors, service suppliers and other external persons have to report at the weigh-scale upon arrival and departure. <sup>\*1 \*2</sup>
- Visitors, suppliers and service providers must report to the office upon arrival and departure. <sup>\*3</sup>
- The instructions of our personnel must be followed.
- After official receipt by our personnel, scrap and waste delivered is assumed to be our property.
- Any kind of theft will be prosecuted.
- Violations against this safety information and framework conditions justify refusal of acceptance and will be sanctioned with exclusion.

## Liability

- Entering and driving on the plant premises is done at own risk.
- We will not assume any liability for accidents or other harmful events in all of the plant premises as long as they were not caused intentionally or negligently by us.
- Damages of any kind, including environmental damage, caused by the delivery of unauthorized scrap, waste of material mixtures, the creator of such waste and the deliverer are jointly and severally liable.
- Personnel of third party companies is liable for damages caused by them, in addition also the employer of this personnel.
- We are not liable for the cost of transporting or expense caused by the rejection of scrap, waste or material mixtures or ending receiving, caused by interruption of operations or other time delays.

## Composition of Scrap and Waste

- Scrap and waste must conform with our criteria for acceptance (European Scrap Type Listing, special contracts)
- Every delivery is weighed by our personnel, inspected and evaluated.

## Hazards on the Premises



Driving with open – or unsecured container doors is prohibited. Presence in the hazardous area of excavators and cranes is prohibited.



Pay attention to traffic during plant operation (fork-lifts, wheel-loaders, excavators) <sup>\*1-3</sup> (cranes, trains etc.) <sup>\*1 \*2</sup> Drivers have a limited field of vision.



Attention! Suspended loads and pieces of scrap flying around. <sup>\*1 -3</sup>



Attention! Detonation activity, watch for sound signals! <sup>\*1</sup>



Intense heat close to slag beds. Keep your distance. Do not pour hot slag into water. Risk of deflagration. <sup>\*4</sup>



Danger of stumbling because of uneven ground and scrap pieces lying around.



Danger of falling on platforms and quay wall. <sup>\*1-2</sup>



Danger of slipping because of slippery or oil trenched ground.



Danger from track traffic (trains, cranes) They always have the right of way. <sup>\*1 \*2</sup>

## First Aid, Escape Routes and Assembly Stations



First aid / Medical Kit



Eye washes



Follow escape and rescue routes. Keep these routes free.



In case of fire, go to assembly stations



Fire extinguishing devices



Fire extinguisher

## Your personal protective clothing consists of:



In principle, entering the plant premises is only permitted with a helmet, safety shoes of Classification 3 and a safety vest. Please always use the handrail on stairs.



In marked areas, please use further PSE, like hearing protection, safety glasses, gloves <sup>\*1-4</sup> or swimming vests. <sup>\*1 \*2</sup>